


## Ventilation Assessment Summary



#	HVAC		Site		Air Changes			Recommendation	
	Room	Туре	Campus	Building	Target	Actual	Result	Min. CADR	Min. Supply
1	D107	Classroom	Laney College	Building D	6	0.0	Does not meet target	540	594
2	<u>D100</u>	Dance/Aerobics	Laney College	Building D	3	0.0	Does not meet target	1164	1281