


## Ventilation Assessment Summary



#	HVAC		Site		Air Changes			Recommendation		Mitigation
	Room	Туре	Campus	Building	Target	Actual	Result	Min. CADR	Min. Supply	Applied CADR
1	<u>D107</u>	Classroom	Laney College	Building D	6	7.7	Meets target with mitigation	540	594	690
2	<u>D100</u>	Dance/Aerobics	Laney College	Building D	3	3.0	Meets target with mitigation	1164	1281	1180